

## LDV REPLACEMENT PARTS

AS PART NO.	LDV PART NO.	DESCRIPTION
AS14295	LBU6136/6146	Steering Box Repair Kit
AS11207	-	Diff. Pinion Seal 2.062"x3.160"x0.500" - Sherpa
AS17744	-	Tie Rod - Cub